Monday, 1/8/2007 10:50:27 AM Date: User: Kim Johnston **Process Sheet** : SUPPORT ASSEMBLY **Drawing Name** : CU-DAR001 Dart Helicopters Services Customer Job Number : 30150 : 10464 **Estimate Number** : NIA : D3278041 **Part Number** P.O. Number : D3278 REV. B : 1/8/2007 S.O. No. : 1/1A **Drawing Number** This Issue : N/A **Project Number** : NC Prsht Rev. : N/A : SMALL /MED FAB **Drawing Revision** First Issue :NIA : 29647 Material **Previous Run** : 1/20/2007 Qty: Each **Due Date** Written By **Checked & Approved By** New issue KJ/JLM : Est:A 94.04.19 Comment **Additional Product** Job Number: Description: Seq. #: **Machine Or Operation:** SUPPORT 1.0 30150A Comment: Sub-Component SUPPORT B29647A X14 + 1 X D3278-1 B 30150B 2.0 Comment: Sub-Component SUPPORT 1 X D3278-2 B 2 2 2 2 7 3 B + D32783 3.0 1.0000 Each(s)/Unit 50,0000 Each(s) Comment: Qty.: Total: Spacer B29652-X5 Pick: Description Qty Part Number B29652 WM 10x Spacer D3278-3 RIVET MS20426AD37 4.0 4.0000 Each(s)/Unit 200.0000 Each(s) Total: Comment: Qty.: **RIVET** Pick: Description Batch Qty Part Number Rivet MS20426AD3 SMALL & MEDIUM FAB RESOURCE 1 SMALL FAB 5.0 Comment: SMALL & MEDIUM FAB RESOURCE 1 Rivet spacers with support as per Dwg D3278.

Page 1

Form: rprocess

Monday, 1/8/2007 10:50:28 AM te: Kim'Johnston **Process Sheet** /ser: **Drawing Name: SUPPORT ASSEMBLY** Customer: CU-DAR001 Dart Helicopters Services Part Number: D3278041 Job Number: 30150 Job Number: Description: **Machine Or Operation:** Seq. #: INSPECT WORK TO CURRENT STEP QC5 6.0 30 31 Comment: INSPECT WORK TO CURRENT STEP Mounting Lug 7.0 D22301 100.0000 Each(s) 2.0000 Each(s)/Unit Total: Comment: Qty.: Mounting Lug 260 Pick: Packing Kit Qty Part Number Description Batch Mounting Lug D2230-1 2 Bolt AN413A 8.0 100.0000 Each(s) 2.0000 Each(s)/Unit Total: Comment: Qty.: M101938 X Bolt Pick: Packing Kit Description Batch Qty Part Number 102630 Bolt AN4-13A Washer AN960JD416 9.0 200 0000 Each(s) 4.0000 Each(s)/Unit Total: Comment: Qty.: Washer Pick: Packing Kit Description Batch Qty Part Number m 101938 Washer AN960JD416 MS21042L4 10.0 2.0000 Each(s)/Unit Total: 100.0000 Each(s) Comment: Qty.: Nut Pick: Packing Kit X60 1 Qty Part Number Description Batch 9/85 MS21042L4 Nut 2 SMALL & MEDIUM FAB RESOURCE 1 11.0 SMALL FAB 1 x30 Comment: SMALL & MEDIUM FAB RESOURCE 1 Assemble support as per Dwg D3278. ***DO NOT TIGHTEN BOLTS*** Identify as D3278-041

Form: rprocess

Page 2

æ: ₃er: Monday, 1/8/2007 10:50:28 AM

Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: SUPPORT ASSEMBLY

Job Number: 30150

Part Number: D3278041

Job Number:



Seq. #:

Machine Or Operation:

Description:

12.0

INSPECT WORK TO CURRENT STEP



WORK TO CURRENT STEP Comment: INSPECT



*3*0

13.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and Stock

Location: STICE

QC21 14.0



Comment: FINAL INSPECTION/W/O RELEASE


Job Completion




U 62.02.02



	DESIGN DRAWN BY		DRAWN BY	DART AEROSPACE I HAWKESBURY, ONTARIO, CANADA	LTD		
Ì	CHECK	(ED #	APPROVED #	DRAWING NO. D3278	SHEET		3
	DATE 05.03.31			TITLE SUPPORT ASSEMBLY		SCA N	LE TS
	Α		04.03.03	NEW ISSUE			
	В		05.03.31	CHANGE DIM/TOL TO ENSURE	FIT	.	



D3278-041 SUPPORT ASSEMBLY



Copyright © 2004 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.